




MAINTENANCE PREVENTIVE / PREVENTIVE MAINTENANCE

LOT	REP	QT	REF	DESIGNATION	/	/	DESIGNATION
D1		1	3050879700F	LOT DE CLAPET	/	/	SET OF VALVES
	024	1		SIEGE	/ D15.9	/	SEAT
	437	1		BILLE	/ D.15.9	/	BALL
	438	2		JOINT TORIQUE	/ 20.29x2.62	/	ORING
F2		1	3071240046F	LOT DE MAINTENANCE	/	/	MAINTENANCE KIT
	024	2		SIEGE	/ D15.9	/	SEAT
	305	1		ENS.MEMBRANE	/ D.82	/	DIAPHRAGM ASSY
	437	2		BILLE	/ D.15.9	/	BALL
	438	4		JOINT TORIQUE	/ 20.29x2.62	/	ORING

MAINTENANCE CORRECTIVE / CORRECTIVE MAINTENANCE

LOT	REP	QT	REF	DESIGNATION	/	/	DESIGNATION
A1	019	1	01903930078N	RONDELLE	/ 40 GM	/	WASHER
B2	045	2	0450420078N	RACCORD	/ 1"-1/2"	/	SCREWED CONNECTION
C3		2	3050870008F	ENSEMBLE CLAPET	/	/	CHECK VALVE ASSEMBLY
	003	1		CORPS DE BOITE A CLAPET	/ D.15.9	/	CHECK VALVE BODY
	024	1		SIEGE	/ D15.9	/	SEAT
	437	1		BILLE	/ D.15.9	/	BALL
	438	2		JOINT TORIQUE	/ 20.29x2.62	/	ORING
E4	305	1	3050976130N	ENS.MEMBRANE	/ D.82	/	DIAPHRAGM ASSY
G5		1	3071240177F	ENSEMBLE CORPS DE DOSEUR	/ 40.0/50.0	/	BODY LIQUID END ASSEMBLY
	021	1		CORPS DE DOSEUR	/ 40	/	LIQUID END BODY
	434	6		RONDELLE MU	/ D.8	/	WASHER MU
	435A	6		ECROU H	/ M8	/	NUT H
	435	6		VIS H	/ M8X80 - 22	/	SCREW H

D40N9/Z dupla membrános ATEX fej
 1 double diaphragm kit Pièces de rechange
 Double diaphragm kit to rebuilding
 GM120D40N/C5.....(without manometer... -
 includes : spacer (tambourin)
 09803990078n) + double diaphragm kit
 (3050983311n) + (6) screws 4350035675n.....
 For modification of pump 21008713..... NET
 PRICE - Your discount is deducted

2 4320345000N MANOMETRE 0-10 BAR D.63 G1/4 T